



State of New Jersey  
Department of Community Affairs  
Division of Codes and Standards  
Bureau of Housing Inspection

**INSPECTION REPORT AND ORDERS OF THE COMMISSIONER**

**Registration #:** 1915023375  
**Notice #:** 29838342  
**Issuance Date:** January 18, 2019  
**Inspector(s):** DEBORAH STECKLER

**Inspection Type:** 1st Reinspection of 08/28/2018 Cyclical  
**Inspection Date:** 12/18/2018  
**Re-inspection Date:** Refer to Enclosed Penalty

**Owner Information:** BROOKSIDE REALTY URBAN  
RENEWAL LLC  
C/O MICHAEL WIEDER  
691 ELIZABETH AVENUE  
#2  
Newark, NJ 07112  
9732821100x012

**Property Information:** 33 MILL STREET  
33 MILL Street  
Newton Town, Sussex County

**Property Type:** Multiple Dwelling  
**Buildings:** 3  
**Apartments:** 0  
**Dwelling Units:** 221  
**Total Units:** 221

Please take notice that the Inspections conducted by the New Jersey Bureau of Housing Inspection at the premises noted above disclosed that violations listed below exist at said premises in contravention of the Hotel Multiple Dwelling Law and of the "Regulations for the Maintenance of Hotels and Multiple Dwellings" promulgated there under. You are hereby ORDERED by the Commissioner to comply with all of the following orders and to correct all the violations listed below by the date listed above. Failure to comply with this notice and Orders of the Commissioner will subject you to a penalty levied by the Department of Community Affairs in accordance with the provisions of the Hotel and Multiple Dwelling Law (P.L. 1967, C76) as amended and supplemented; N.J.S.A. 55:13A-1 et seq.

Lt. Governor  
Sheila Y. Oliver,  
Commissioner, Community Affairs

A handwritten signature in black ink, appearing to read "Edwin Tomkiewicz".

By: Edwin Tomkiewicz, Chief, Bureau of Housing Inspection

**ATTENTION - PLEASE READ FURTHER INSTRUCTIONS AT END OF REPORT**

## **OPEN VIOLATIONS**

PLEASE REFER TO THE PERMIT INFORMATION AT THE END OF THIS REPORT FOR CORRECTIVE ACTIONS WITH A FOOTNOTE OF a "P" or "M". ANY VIOLATION CITED IN THIS REPORT SHALL BE CORRECTED AND SHALL BE MAINTAINED AND/OR KEPT IN AN OPERATIVE CONDITION AT ALL TIMES PURSUANT TO N.J.A.C. 5:10-1.6 AND/OR N.J.A.C. 5:70 ET SEQ.

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900871	Building 1 33 MILL Street	Building 1 - Exterior	Entire Building	Caulk window frames to prevent the penetration of moisture or infestation [N.J.A.C. 5:10-7.4]	N	Unabated
3900966	Building 1 33 MILL Street	Building 1 - Common	Elevator- Elevator 2 Side	Maintain in each elevator a mirror that will enable persons, prior to entering into such elevator, to view the inside thereof to determine whether any person is in such elevator [N.J.A.C. 5:10-12.4]	N	Unabated
3900965	Building 1 33 MILL Street	Building 1 - Common	Elevator- Elevator1 Front	Maintain in each elevator a mirror that will enable persons, prior to entering into such elevator, to view the inside thereof to determine whether any person is in such elevator [N.J.A.C. 5:10-12.4]	N	Unabated
3900846	Building 1 33 MILL Street	Building 1 - Common	Entire Building- repair fan&clean ductwork all units/all levels	REPAIR OR REPLACE MECHANICAL BATHROOM VENTILATION TO EXHAUST AT LEAST 40 CUBIC FEET OF AIR PER MINUTE PER URINAL OR TOILET *M [N.J.A.C. 5:10-16.3(a)4]	N	Undetermined
3900845	Building 1 33 MILL Street	Building 1 - Common	Entire Building- repair fan&clean ductwork all units/all levels	REPAIR OR REPLACE KITCHEN VENTILATION EXHAUST SYSTEM TO EXHAUST AT LEAST 2 CUBIC FEET OF AIR PER MINUTE PER SQUARE FOOT OF FLOOR AREA DIRECTLY TO THE OUTSIDE. *M [N.J.A.C. 5:10-16.3(a)1]	N	Undetermined
3900860	Building 1 33 MILL Street	Building 1 - Common	Hallway-near 9N	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900864	Building 1 33 MILL Street	Building 1 - Common	Lobby	Keep posted at all times, in a conspicuous location on the premises, a copy of the current certificate of inspection issued pursuant to the Uniform Fire Safety Act for a building subject to the Act, that is deemed a life hazard use pursuant to N.J.A.C. 5:70-2.4 through 2.4D [N.J.A.C. 5:10-1.12(e)2]	N	Unabated
3900847	Building 1 33 MILL Street	Building 1 - Common	side door lower level repair intercom system	Repair or replace door latch release system. [N.J.A.C. 5:10-19.2(a)8]	N	Unabated
3899962	Building 1 33 MILL Street	Unit 1A, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899961	Building 1 33 MILL Street	Unit 1A, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900236	Building 1 33 MILL Street	Unit 1A, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3899963	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899964	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900237	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900317	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Kitchen	Secure kitchen cabinet to wall [N.J.A.C. 5:10-20.1(a)7]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900318	Building 1 33 MILL Street	Unit 1B, Floor 1, Building 1	Kitchen	Occupants shall place storage in a manner as to not create a hazard [N.J.A.C. 5:10-5.1(d)]	N	Unabated
3899965	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899966	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900238	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900322	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Living Room-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900321	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Living Room-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900324	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3899967	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899968	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899972	Building 1 33 MILL Street	Unit 1E, Floor 1, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3899971	Building 1 33 MILL Street	Unit 1E, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900241	Building 1 33 MILL Street	Unit 1E, Floor 1, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900330	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3899974	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899973	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900242	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900799	Building 1 33 MILL Street	Unit 10M, Floor 10, Building 1	Entire Unit	Do not operate portable, electric space heaters within 3 feet (914 mm) of combustible materials or in locations for which they are not listed [N.J.A.C. 5:70-3,605.10.4]	Y	Undetermined
3899823	Building 1 33 MILL Street	Unit 10M, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3899824	Building 1 33 MILL Street	Unit 10M, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900167	Building 1 33 MILL Street	Unit 10M, Floor 10, Building 1	Entire Unit- remove substances from heating/ cooling	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			plenums			
3899846	Building 1 33 MILL Street	Unit 10N, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899845	Building 1 33 MILL Street	Unit 10N, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900178	Building 1 33 MILL Street	Unit 10N, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900800	Building 1 33 MILL Street	Unit 10N, Floor 10, Building 1	Kitchen	Repair or replace kitchen cabinets, cabinet doors or drawers to open and close properly. [N.J.A.C. 5:10-20.1(a)7]	N	Undetermined
3900802	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900801	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900803	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3899868	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899867	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900189	Building 1 33 MILL Street	Unit 10P, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899890	Building 1 33 MILL Street	Unit 10Q, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899889	Building 1 33 MILL Street	Unit 10Q, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900200	Building 1 33 MILL Street	Unit 10Q, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3899911	Building 1 33 MILL Street	Unit 10R, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3899912	Building 1 33 MILL Street	Unit 10R, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900211	Building 1 33 MILL Street	Unit 10R, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900805	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Undetermined
3900804	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Bathroom-sink/basin	Repair or replace faucet *M [N.J.A.C. 5:10-21.1(e)]	N	Undetermined
3899934	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899933	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900222	Building 1 33 MILL Street	Unit 10S, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900807	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit	Refrain from passing extension cord across any path of travel [N.J.A.C. 5:10-13.1(d)4]	N	Undetermined
3900808	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit	Extension cords must not be used in place of permanent wiring. *M [N.J.A.C. 5:70-3,605.5]	Y	Undetermined
3899949	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3899950	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900230	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900806	Building 1 33 MILL Street	Unit 10T, Floor 10, Building 1	Kitchen	REPAIR FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3899952	Building 1 33 MILL Street	Unit 10U, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899951	Building 1 33 MILL Street	Unit 10U, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900231	Building 1 33 MILL Street	Unit 10U, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900339	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3899976	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899975	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900243	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3899978	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899977	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900244	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900351	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900350	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900348	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900349	Building 1 33 MILL Street	Unit 2B, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900356	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Bathroom- repair leak then repair ceiling tile	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3899979	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899980	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900245	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900354	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900353	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900355	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900361	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom- Bedroom 1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900364	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom- Bedroom 1	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900367	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom- Bedroom 1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900358	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom- Bedroom 1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900359	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom- Bedroom 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900365	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom- Bedroom 2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900362	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom- Bedroom 2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900368	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Bedroom- Bedroom 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3899981	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3899982	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900246	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900363	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900357	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900360	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900366	Building 1 33 MILL Street	Unit 2D, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900373	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900374	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900375	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3899983	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899984	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900247	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900372	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900382	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 1	Repair woodwork to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900385	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900376	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900379	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900388	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	REPLACE FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900386	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900383	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	Repair woodwork to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900380	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900389	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	Replace broken glass [N.J.A.C. 5:10-7.3(c)]	N	Undetermined
3900390	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	repair windows [N.J.A.C. 5:10-7.4]	N	Undetermined
3900377	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Bedroom-BR 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899986	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899985	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900248	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900381	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900378	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900384	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Living Room	Repair woodwork to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900387	Building 1 33 MILL Street	Unit 2F, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3899987	Building 1 33 MILL Street	Unit 3A, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899988	Building 1 33 MILL Street	Unit 3A, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900249	Building 1 33 MILL Street	Unit 3A, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900391	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900395	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3899990	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899989	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900250	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900392	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900396	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900398	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900394	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3899994	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899993	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900252	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900415	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900407	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 2- repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900409	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 2- repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900413	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 2- repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900411	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 2- repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3899996	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899995	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900253	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900414	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Front Door	Install chain guard on entry door(s). [N.J.A.C. 5:10-19.2(a)5]	N	Unabated
3899998	Building 1 33 MILL Street	Unit 3E, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899997	Building 1 33 MILL Street	Unit 3E, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900254	Building 1 33 MILL Street	Unit 3E, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900000	Building 1 33 MILL Street	Unit 3F, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899999	Building 1 33 MILL Street	Unit 3F, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900255	Building 1 33 MILL Street	Unit 3F, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900002	Building 1 33 MILL Street	Unit 3G, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900001	Building 1 33 MILL Street	Unit 3G, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900256	Building 1 33 MILL Street	Unit 3G, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900003	Building 1 33 MILL Street	Unit 3H, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900004	Building 1 33 MILL Street	Unit 3H, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900257	Building 1 33 MILL Street	Unit 3H, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900006	Building 1 33 MILL Street	Unit 3J, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900005	Building 1 33 MILL Street	Unit 3J, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900258	Building 1 33 MILL Street	Unit 3J, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900008	Building 1 33 MILL Street	Unit 3K, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900007	Building 1 33 MILL Street	Unit 3K, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900259	Building 1 33 MILL Street	Unit 3K, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900009	Building 1 33 MILL Street	Unit 3L, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
			leaks			
3900010	Building 1 33 MILL Street	Unit 3L, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900260	Building 1 33 MILL Street	Unit 3L, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900011	Building 1 33 MILL Street	Unit 3M, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900012	Building 1 33 MILL Street	Unit 3M, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900261	Building 1 33 MILL Street	Unit 3M, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900016	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900015	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900263	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900420	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900418	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900421	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Bathroom-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900423	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Bathroom-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900425	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Bathroom-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900427	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Bathroom-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900017	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900018	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900264	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900422	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Living Room-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900424	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Living Room-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900428	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Living Room- repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900426	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Living Room- repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900432	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900430	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900020	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900019	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900265	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900437	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900435	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900021	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900022	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900266	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900442	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900439	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900440	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900441	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900443	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900024	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900023	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900267	Building 1 33 MILL Street	Unit 3S, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900025	Building 1 33 MILL Street	Unit 3V, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900026	Building 1 33 MILL Street	Unit 3V, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900268	Building 1 33 MILL Street	Unit 3V, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900446	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900447	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900448	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N	Unabated
3900445	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900444	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900028	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900027	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900269	Building 1 33 MILL Street	Unit 3W, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900029	Building 1 33 MILL Street	Unit 3X, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900030	Building 1 33 MILL Street	Unit 3X, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900270	Building 1 33 MILL Street	Unit 3X, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900449	Building 1 33 MILL Street	Unit 3X, Floor 3, Building 1	Kitchen	Repair or replace refrigerator to maintain temperatures between 32 and 50 degrees to avoid food spoilage. [N.J.A.C. 5:10-20.1(a)5]	N	Unabated
3900032	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900031	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900271	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900453	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900452	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900451	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900450	Building 1 33 MILL Street	Unit 3Y, Floor 3, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900455	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bedroom- repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900456	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bedroom- repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900454	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bedroom- repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900457	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bedroom- repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900034	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900033	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900272	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900462	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Living Room- repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900459	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Living Room- repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900460	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Living Room- repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900461	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Living Room- repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900037	Building 1 33 MILL Street	Unit 4B, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900038	Building 1 33 MILL Street	Unit 4B, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900274	Building 1 33 MILL Street	Unit 4B, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900040	Building 1 33 MILL Street	Unit 4C, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900039	Building 1 33 MILL Street	Unit 4C, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900275	Building 1 33 MILL Street	Unit 4C, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900042	Building 1 33 MILL Street	Unit 4D, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900041	Building 1 33 MILL Street	Unit 4D, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900276	Building 1 33 MILL Street	Unit 4D, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900043	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900044	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900277	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900046	Building 1 33 MILL Street	Unit 4F, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900045	Building 1 33 MILL Street	Unit 4F, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900278	Building 1 33 MILL Street	Unit 4F, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900048	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900047	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			leaks			
3900279	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900050	Building 1 33 MILL Street	Unit 4H, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900049	Building 1 33 MILL Street	Unit 4H, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900280	Building 1 33 MILL Street	Unit 4H, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900483	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900052	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900051	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900281	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900054	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900053	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900282	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900485	Building 1 33 MILL Street	Unit 4L, Floor 4, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900056	Building 1 33 MILL Street	Unit 4L, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900055	Building 1 33 MILL Street	Unit 4L, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900283	Building 1 33 MILL Street	Unit 4L, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900488	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900486	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900487	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900489	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900060	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900059	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900285	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900490	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Entire Unit- repair windws to readily open&close	repair windows [N.J.A.C. 5:10-7.4]	N	Unabated
3900492	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Front Door	Install chain guard on entry door(s). [N.J.A.C. 5:10-19.2(a)5]	N	Unabated
3900062	Building 1 33 MILL Street	Unit 4N, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900061	Building 1 33 MILL Street	Unit 4N, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900286	Building 1 33 MILL Street	Unit 4N, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900063	Building 1 33 MILL Street	Unit 4P, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900064	Building 1 33 MILL Street	Unit 4P, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900287	Building 1 33 MILL Street	Unit 4P, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900066	Building 1 33 MILL Street	Unit 4Q, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900065	Building 1 33 MILL Street	Unit 4Q, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900288	Building 1 33 MILL Street	Unit 4Q, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900499	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900498	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900497	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900496	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900495	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900068	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900067	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900289	Building 1 33 MILL Street	Unit 4R, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900070	Building 1 33 MILL Street	Unit 4S, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900069	Building 1 33 MILL Street	Unit 4S, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900290	Building 1 33 MILL Street	Unit 4S, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900071	Building 1 33 MILL Street	Unit 4T, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900072	Building 1 33 MILL Street	Unit 4T, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900291	Building 1 33 MILL Street	Unit 4T, Floor 4, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900074	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900073	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
			leaks			
3900292	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900505	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900504	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900502	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900503	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900076	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900075	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900293	Building 1 33 MILL Street	Unit 4V, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900508	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900507	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900506	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900509	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Bedroom-BR 2-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900078	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900077	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900294	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900513	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900511	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900515	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900517	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900519	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Bedroom- closet door BR-2	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900081	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900082	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900296	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900514	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900516	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900518	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900512	Building 1 33 MILL Street	Unit 4X, Floor 4, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900520	Building 1 33 MILL Street	Unit 4Y, Floor 4, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900084	Building 1 33 MILL Street	Unit 4Y, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900083	Building 1 33 MILL Street	Unit 4Y, Floor 4, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900297	Building 1 33 MILL Street	Unit 4Y, Floor 4, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900521	Building 1 33 MILL Street	Unit 5A, Floor 5, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900086	Building 1 33 MILL Street	Unit 5A, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900085	Building 1 33 MILL Street	Unit 5A, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900298	Building 1 33 MILL Street	Unit 5A, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900087	Building 1 33 MILL Street	Unit 5B, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900088	Building 1 33 MILL Street	Unit 5B, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900299	Building 1 33 MILL Street	Unit 5B, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900522	Building 1 33 MILL Street	Unit 5D, Floor 5, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900091	Building 1 33 MILL Street	Unit 5D, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900092	Building 1 33 MILL Street	Unit 5D, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900301	Building 1 33 MILL Street	Unit 5D, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900094	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900093	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900302	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900526	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900525	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900524	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900523	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Entire Unit- repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900528	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Hallway	Provide and install a visual alarm type carbon monoxide detector for unit, at request of tenant of a multiple dwelling unit in which a person who is deaf or hearing-	Y	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
				impaired resides *M [N.J.A.C. 5:10-28.1(c)]		
3900527	Building 1 33 MILL Street	Unit 5E, Floor 5, Building 1	Hallway	Install, at the request of a tenant of a unit in building of Use Group R-2 in which a person who is deaf or hearing-impaired resides, a visual alarm type smoke detector for that unit or, in the case of a rooming or boarding house resident, for that resident's sleeping area *M [N.J.A.C. 5:70-4.9(a)3vii]	Y	Unabated
3900096	Building 1 33 MILL Street	Unit 5F, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900095	Building 1 33 MILL Street	Unit 5F, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900303	Building 1 33 MILL Street	Unit 5F, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900097	Building 1 33 MILL Street	Unit 5G, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900098	Building 1 33 MILL Street	Unit 5G, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900304	Building 1 33 MILL Street	Unit 5G, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900100	Building 1 33 MILL Street	Unit 5H, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900099	Building 1 33 MILL Street	Unit 5H, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900305	Building 1 33 MILL Street	Unit 5H, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900104	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900103	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900307	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900531	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900529	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900105	Building 1 33 MILL Street	Unit 5K, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900106	Building 1 33 MILL Street	Unit 5K, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900308	Building 1 33 MILL Street	Unit 5K, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900108	Building 1 33 MILL Street	Unit 5L, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3900107	Building 1 33 MILL Street	Unit 5L, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900309	Building 1 33 MILL Street	Unit 5L, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900535	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900109	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900110	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900310	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900112	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900111	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900311	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900115	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900116	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900313	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900118	Building 1 33 MILL Street	Unit 5R, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900117	Building 1 33 MILL Street	Unit 5R, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900314	Building 1 33 MILL Street	Unit 5R, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900120	Building 1 33 MILL Street	Unit 5S, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900119	Building 1 33 MILL Street	Unit 5S, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900315	Building 1 33 MILL Street	Unit 5S, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900122	Building 1 33 MILL Street	Unit 5T, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			leaks			
3900121	Building 1 33 MILL Street	Unit 5T, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900316	Building 1 33 MILL Street	Unit 5T, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3899738	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899737	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900124	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3899740	Building 1 33 MILL Street	Unit 5V, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899739	Building 1 33 MILL Street	Unit 5V, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900125	Building 1 33 MILL Street	Unit 5V, Floor 5, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3899742	Building 1 33 MILL Street	Unit 5W, Floor 5, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899741	Building 1 33 MILL Street	Unit 5W, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900126	Building 1 33 MILL Street	Unit 5W, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900556	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom- remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900555	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom- remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900554	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom- remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900553	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom- remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3899744	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899743	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900127	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900560	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900559	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900558	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900557	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3899746	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899745	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900128	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3899747	Building 1 33 MILL Street	Unit 6A, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899748	Building 1 33 MILL Street	Unit 6A, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900129	Building 1 33 MILL Street	Unit 6A, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900562	Building 1 33 MILL Street	Unit 6B, Floor 6, Building 1	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899750	Building 1 33 MILL Street	Unit 6B, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899749	Building 1 33 MILL Street	Unit 6B, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900130	Building 1 33 MILL Street	Unit 6B, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900567	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Bedroom-BR 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900565	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Bedroom-BR 2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900563	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Bedroom-BR 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900569	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Entire Unit	Eliminate Nuisance Oder which shall constitute a nuisance that is harmful or potentially harmful to the health and well-being of persons of ordinary sensitivity occupying or using the premises. [N.J.A.C. 5:10-6.2]	N	Unabated
3899754	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899753	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900132	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			plenums			
3900571	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900583	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900579	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900580	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900576	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900572	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3899755	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899756	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3900133	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900570	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Kitchen	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900574	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Kitchen	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900578	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Kitchen	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900582	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Kitchen	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900585	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900577	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900581	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900573	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3899760	Building 1 33 MILL Street	Unit 6F, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899759	Building 1 33 MILL Street	Unit 6F, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900135	Building 1 33 MILL Street	Unit 6F, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900586	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900587	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900589	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900588	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3899764	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899763	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900137	Building 1 33 MILL Street	Unit 6H, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900590	Building 1 33 MILL Street	Unit 6J, Floor 6, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3899766	Building 1 33 MILL Street	Unit 6J, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899765	Building 1 33 MILL Street	Unit 6J, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900138	Building 1 33 MILL Street	Unit 6J, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900592	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900594	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900596	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900598	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900593	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Workspace	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900595	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Workspace	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900599	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Workspace	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900597	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Workspace	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900602	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Bedroom- BR-1-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900601	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Bedroom- BR-1-remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900600	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Bedroom- BR-1-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900603	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Bedroom- BR-1-remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900604	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Entire Unit	Occupants shall place all garbage within receptacles provided to avoid unsanitary conditions [N.J.A.C. 5:10-5.4(a)]	N	Undetermined
3899776	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899775	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900143	Building 1 33 MILL Street	Unit 6P, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900606	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3899783	Building 1 33 MILL Street	Unit 6S, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3899784	Building 1 33 MILL Street	Unit 6S, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			leaks			
3900147	Building 1 33 MILL Street	Unit 6S, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900611	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900613	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900616	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900617	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900621	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3899796	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Unabated
3899795	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Unabated
3900153	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Unabated
3900630	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900626	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900628	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900622	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900624	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3899806	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899805	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900158	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900627	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900629	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900623	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900625	Building 1 33 MILL Street	Unit 7D, Floor 7, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3899808	Building 1 33 MILL Street	Unit 7E, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899807	Building 1 33 MILL Street	Unit 7E, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900159	Building 1 33 MILL Street	Unit 7E, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900648	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900661	Building 1 33 MILL Street	Unit 7S, Floor 7, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900668	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N	Undetermined
3900667	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900665	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900664	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900683	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Kitchen	Occupant shall keep cooking equipment clean, free of garbage, food particles and grease. [N.J.A.C. 5:10-5.4(f)]	N	Unabated
3900687	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900686	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Hallway	REPAIR FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900685	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Living Room	REPAIR FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900689	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900694	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Undetermined
3900696	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N	Undetermined
3899880	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Undetermined
3899879	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Undetermined
3900195	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900695	Building 1 33 MILL Street	Unit 8Q, Floor 8, Building 1	Hallway	Provide Unrestricted Passage Thru Hallways. [N.J.A.C. 5:10-8.3(b)]	Y	Unabated
3900900	Building 2 33 MILL Street	Building 2 - Exterior	Entire Building	Relocate open-flame cooking device a minimum of 5 feet from combustible construction *M [N.J.A.C. 5:70-3.308(1)4]	Y	Unabated
3900905	Building 2 33 MILL Street	Building 2 - Common	Garage	Interconnected common area smoke detection system shall be on circuitry that is connected into the building owner's electric meter. *P [N.J.A.C. 5:70-4.9(a)3i]	Y	Unabated
3900903	Building 2 33 MILL Street	Building 2 - Common	Garage	Install AC powered constantly active electrical hard wired interconnected smoke detectors in all interior common areas, with the approval of the fire protection subcode official, fixed temperature or rate of rise combination heat detectors may be substituted for smoke detectors where frequent nuisance alarms would be likely to occur. *p [N.J.A.C. 5:70-4.9(a)3i]	Y	Unabated
3900904	Building 2 33 MILL Street	Building 2 - Common	Laundry Room	Interconnected common area smoke detection system shall be on circuitry that is connected into the building owner's electric meter. *P [N.J.A.C. 5:70-4.9(a)3i]	Y	Unabated
3900902	Building 2 33 MILL Street	Building 2 - Common	Laundry Room	Install AC powered constantly active electrical hard wired interconnected smoke detectors in all interior common areas, with the approval of the fire protection subcode official, fixed temperature or rate of rise combination heat detectors may be substituted for smoke detectors where frequent nuisance alarms would be likely to occur. *p [N.J.A.C. 5:70-4.9(a)3i]	Y	Unabated
3900906	Building 2 33 MILL Street	Building 2 - Common	interconnect with laundry&garage	Repair exterior fire alarm bell *M [N.J.A.C. 5:70-3.907(8)1]	Y	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900884	Building 2 33 MILL Street	Unit 12, Floor 1, Building 2	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Undetermined
3900883	Building 2 33 MILL Street	Unit 12, Floor 1, Building 2	Front Door	Provide for every unit of dwelling space in hotels and multiple dwellings some permanent and legible identification by letter, number or other symbol at or near the front entrance thereof [N.J.A.C. 5:10-18.2(a)]	N	Unabated
3900886	Building 2 33 MILL Street	Unit 12, Floor 1, Building 2	Living Room	Eliminate Nuisance Oder which shall constitute a nuisance that is harmful or potentially harmful to the health and well-being of persons of ordinary sensitivity occupying or using the premises. [N.J.A.C. 5:10-6.2]	N	Undetermined
3900885	Building 2 33 MILL Street	Unit 12, Floor 1, Building 2	Living Room	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900887	Building 2 33 MILL Street	Unit 14, Floor 1, Building 2	Bathroom	Caulk bathtub/shower [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900893	Building 2 33 MILL Street	Unit 18, Floor 1, Building 2	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900894	Building 2 33 MILL Street	Unit 18, Floor 1, Building 2	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900872	Building 2 33 MILL Street	Unit 20, Floor 1, Building 2	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N	Unabated
3900898	Building 2 33 MILL Street	Unit 26, Floor 1, Building 2	Hallway-1st flr hall	Repair or Replace light fixture *M [N.J.A.C. 5:10-13.3(c)]	N	Undetermined
3900899	Building 2 33 MILL Street	Unit 26, Floor 1, Building 2	Kitchen	REPAIR OR REPLACE KITCHEN VENTILATION EXHAUST SYSTEM TO EXHAUST AT LEAST 2 CUBIC	N	Undetermined



Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
				FEET OF AIR PER MINUTE PER SQUARE FOOT OF FLOOR AREA DIRECTLY TO THE OUTSIDE. *M [N.J.A.C. 5:10-16.3(a)1]		
3900873	Building 2 33 MILL Street	Unit 4, Floor 1, Building 2	Entire Unit- provide records of extermination	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N	Unabated
3900877	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Bedroom- middle bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900879	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Bedroom- middle bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900876	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Hallway-2nd flr hall	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900878	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Hallway-2nd flr hall	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900880	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Kitchen	REPAIR OR REPLACE KITCHEN VENTILATION EXHAUST SYSTEM TO EXHAUST AT LEAST 2 CUBIC FEET OF AIR PER MINUTE PER SQUARE FOOT OF FLOOR AREA DIRECTLY TO THE OUTSIDE. *M [N.J.A.C. 5:10-16.3(a)1]	N	Unabated
3900875	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900874	Building 2 33 MILL Street	Unit 8, Floor 1, Building 2	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900964	Building 3 33 MILL Street	Building 3 - Exterior	Entire Building	Relocate open-flame cooking device a minimum of 5 feet from combustible construction *M [N.J.A.C. 5:70-3.308(1)4]	Y	Unabated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900962	Building 3 33 MILL Street	Building 3 - Exterior	Entire Building	Repair foundation wall to be free of cracks and holes. *M [N.J.A.C. 5:10-7.2]	N	Unabated
3900961	Building 3 33 MILL Street	Building 3 - Common	Entire Building	Waterproof crawl space to prevent the penetration of Water or other Sources of Moisture. [N.J.A.C. 5:10-8.1(a)]	N	Unabated
3900959	Building 3 33 MILL Street	Building 3 - Common	Utility Room- interconnect with exterior bell	Install AC powered constantly active electrical hard wired interconnected smoke detectors in all interior common areas, with the approval of the fire protection subcode official, fixed temperature or rate of rise combination heat detectors may be substituted for smoke detectors where frequent nuisance alarms would be likely to occur. *p [N.J.A.C. 5:70-4.9(a)3i]	Y	Unabated
3900960	Building 3 33 MILL Street	Building 3 - Common	interconnect with utility room	Repair exterior fire alarm bell *M [N.J.A.C. 5:70-3.907(8)1]	Y	Unabated
3900907	Building 3 33 MILL Street	Unit 28, Floor 1, Building 3	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N	Unabated
3900910	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900911	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Bedroom- master bedroom	Repair or replace electric outlet. [N.J.A.C. 5:10-13.1(b)7]	N	Unabated
3900912	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Entire Unit- cover baseboard units	Cover the heating system, including such parts as heating risers, ducts and hot water lines, with an insulating material or guard to protect occupants and other persons on the premises from receiving burns due to chance contact [N.J.A.C. 5:10-14.3(d)]	N	Unabated
3900908	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Living Room	Correct Inadequate Load Bearing to be Capable of Sustaining Safely Its Own Weight and Loads to	Y	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
				Which they May be Subject To *M [N.J.A.C. 5:10-7.1]		
3900914	Building 3 33 MILL Street	Unit 32, Floor 1, Building 3	Bedroom- front bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900913	Building 3 33 MILL Street	Unit 32, Floor 1, Building 3	Bedroom- front bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900917	Building 3 33 MILL Street	Unit 34, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900918	Building 3 33 MILL Street	Unit 34, Floor 1, Building 3	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900916	Building 3 33 MILL Street	Unit 34, Floor 1, Building 3	Kitchen	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900915	Building 3 33 MILL Street	Unit 34, Floor 1, Building 3	Kitchen	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900925	Building 3 33 MILL Street	Unit 38, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Undetermined
3900926	Building 3 33 MILL Street	Unit 38, Floor 1, Building 3	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Undetermined
3900927	Building 3 33 MILL Street	Unit 38, Floor 1, Building 3	Bathroom-2nd flr	REPAIR OR REPLACE MECHANICAL BATHROOM VENTILATION TO EXHAUST AT LEAST 50 CUBIC FEET OF AIR PER MINUTE IN ROOMS WITH 1 TOILET OR URINAL DIRECTLY TO THE OUTSIDE *M [N.J.A.C. 5:10-16.3(a)3]	N	Undetermined
3900933	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900928	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Front Door	Provide for every unit of dwelling space in hotels and multiple dwellings some permanent and legible identification by letter, number or other symbol at or near the front entrance thereof [N.J.A.C. 5:10-18.2(a)]	N	Unabated
3900929	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900931	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900932	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900930	Building 3 33 MILL Street	Unit 40, Floor 1, Building 3	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900939	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-2nd flr	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900938	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-2nd flr	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900937	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-2nd flr	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900936	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-2nd flr	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Unabated
3900935	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom-repair tub drain/plug	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900934	Building 3 33 MILL Street	Unit 42, Floor 1, Building 3	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900940	Building 3 33 MILL Street	Unit 44, Floor 1, Building 3	Stairwell/ Stairway-stair 1st to 2nd flr	Repair Steps to be Free of Hazards. [N.J.A.C. 5:10-6.4(a)4]	N	Undetermined
3900942	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900943	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900946	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom-2nd flr	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900945	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom-2nd flr	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Unabated
3900955	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Undetermined
3900953	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-2nd flr	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900954	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-2nd flr	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Undetermined
3900952	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-2nd flr	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900951	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom-2nd flr	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Undetermined

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900950	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Bathroom- repair sub floor before floor replacement	REPLACE FLOOR COVERING to be free of hazards. [N.J.A.C. 5:10-8.2(a)]	N	Undetermined
3900948	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Dining Room	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900949	Building 3 33 MILL Street	Unit 50, Floor 1, Building 3	Kitchen	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Undetermined
3900957	Building 3 33 MILL Street	Unit 52, Floor 1, Building 3	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Unabated
3900958	Building 3 33 MILL Street	Unit 52, Floor 1, Building 3	Kitchen	REPAIR OR REPLACE KITCHEN VENTILATION EXHAUST SYSTEM TO EXHAUST AT LEAST 2 CUBIC FEET OF AIR PER MINUTE PER SQUARE FOOT OF FLOOR AREA DIRECTLY TO THE OUTSIDE. *M [N.J.A.C. 5:10-16.3(a)1]	N	Unabated

## **CLOSED VIOLATIONS**

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900869	Building 1 33 MILL Street	Building 1 - Exterior	Balcony-2A	SECURE LOOSE Guardrail's [N.J.A.C. 5:10-7.7(b)]	Y	Abated
3900866	Building 1 33 MILL Street	Building 1 - Exterior	Balcony- remove bees/ hornets from balconies	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N	Abated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900867	Building 1 33 MILL Street	Building Exterior 1 -	Balcony-remove bees/hornets from balconies	Maintain building in in a condition free from infestation [N.J.A.C. 5:10-10.2(a)]	N	Abated
3900870	Building 1 33 MILL Street	Building Exterior 1 -	Entire Building-where leaking	REPAIR ROOF [N.J.A.C. 5:10-7.4]	N	Abated
3900868	Building 1 33 MILL Street	Building Exterior 1 -	Entire Building-where needed including 7A,7U,7V,5V,4Q,2A,2B	Repair balcony *M [N.J.A.C. 5:10-7.3(a)]	N	Abated
3900865	Building 1 33 MILL Street	Building Common 1 -	Entire Building-all hall vents into units without fire damper	Provide fire rated transom/window with material consistent with corridor material *M [N.J.A.C. 5:70-4.11(o)]	Y	Withdrawn
3900848	Building 1 33 MILL Street	Building Common 1 -	Hallway-10 N-R	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Withdrawn
3900852	Building 1 33 MILL Street	Building Common 1 -	Hallway-10W-J	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900851	Building 1 33 MILL Street	Building Common 1 -	Hallway-2A-E	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900850	Building 1 33 MILL Street	Building Common 1 -	Hallway-3M-Q	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900849	Building 1 33 MILL Street	Building Common 1 -	Hallway-5 D-E	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900859	Building 1 33 MILL Street	Building Common 1 -	Hallway-5N-Q	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900862	Building 1 33 MILL Street	Building Common 1 -	Hallway-6M-Q	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900858	Building 1 33 MILL Street	Building 1 - Common	Hallway-6N-Q	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900861	Building 1 33 MILL Street	Building 1 - Common	Hallway-6Y-W	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900857	Building 1 33 MILL Street	Building 1 - Common	Hallway-6Y-W	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900856	Building 1 33 MILL Street	Building 1 - Common	Hallway-8A-D	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900854	Building 1 33 MILL Street	Building 1 - Common	Hallway-8N-S	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900855	Building 1 33 MILL Street	Building 1 - Common	Hallway-8W-J	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900853	Building 1 33 MILL Street	Building 1 - Common	Hallway-9N-Q	Remove from floors visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900863	Building 1 33 MILL Street	Building 1 - Common	Stairwell/ Stairway- flr1-2 nearE	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900320	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Living Room- repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900319	Building 1 33 MILL Street	Unit 1C, Floor 1, Building 1	Living Room- repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900323	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Abated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900325	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900327	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900326	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900329	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900328	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900239	Building 1 33 MILL Street	Unit 1D, Floor 1, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900331	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom- bedroom 1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900337	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom- bedroom 1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900333	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom- bedroom 1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900335	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom- bedroom 1	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900334	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom- bedroom 2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900332	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom- bedroom 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900336	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom- bedroom 2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900338	Building 1 33 MILL Street	Unit 1F, Floor 1, Building 1	Bedroom- bedroom 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899969	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899970	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900240	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900767	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Front Door	Provide for every unit of dwelling space in hotels and multiple dwellings some permanent and legible identification by letter, number or other symbol at or near the front entrance thereof [N.J.A.C. 5:10-18.2(a)]	N	Abated
3900768	Building 1 33 MILL Street	Unit 10A, Floor 10, Building 1	Hallway- closet	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3899991	Building 1 33 MILL Street	Unit 10B, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899992	Building 1 33 MILL Street	Unit 10B, Floor 10, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900251	Building 1 33 MILL Street	Unit 10B, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900769	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900014	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900013	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900262	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900770	Building 1 33 MILL Street	Unit 10C, Floor 10, Building 1	Hallway-closet near bathroom	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900773	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900771	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900774	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900772	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900035	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900036	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900273	Building 1 33 MILL Street	Unit 10D, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900780	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bathroom	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N	Abated
3900775	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900777	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900779	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR2	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900778	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900776	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900058	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900057	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900284	Building 1 33 MILL Street	Unit 10E, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900781	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900782	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900079	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900080	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900295	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900783	Building 1 33 MILL Street	Unit 10F, Floor 10, Building 1	Kitchen-sink drain	Repair or replace kitchen sink sanitary disposal or sewer system*M [N.J.A.C. 5:10-20.1(a)1]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900102	Building 1 33 MILL Street	Unit 10G, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900101	Building 1 33 MILL Street	Unit 10G, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900306	Building 1 33 MILL Street	Unit 10G, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900784	Building 1 33 MILL Street	Unit 10G, Floor 10, Building 1	Kitchen-pantry/closet door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3899736	Building 1 33 MILL Street	Unit 10H, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899735	Building 1 33 MILL Street	Unit 10H, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900123	Building 1 33 MILL Street	Unit 10H, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899757	Building 1 33 MILL Street	Unit 10J, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899758	Building 1 33 MILL Street	Unit 10J, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900134	Building 1 33 MILL Street	Unit 10J, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900786	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Bedroom-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900785	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Bedroom-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900787	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Bedroom-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900788	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Bedroom-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899780	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899779	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900145	Building 1 33 MILL Street	Unit 10K, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900794	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900793	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bathroom-sink/basin	Repair or replace faucet *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900791	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bedroom-repair leak then repair & paint all	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900789	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bedroom-repair leak then repair & paint all	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900790	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bedroom-repair leak then repair & paint all	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900792	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Bedroom-repair leak then repair & paint all	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899802	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899801	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900156	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900796	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Living Room-repair leak then repair & paint all	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900795	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Living Room-repair leak then repair & paint all	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900797	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Living Room-repair leak then repair & paint all	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900798	Building 1 33 MILL Street	Unit 10L, Floor 10, Building 1	Living Room-repair leak then repair & paint all	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900810	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900816	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900812	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900814	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3899953	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899954	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900232	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900813	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900811	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900809	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900815	Building 1 33 MILL Street	Unit 10V, Floor 10, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900825	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR1	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900821	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900817	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900829	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900818	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900830	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900833	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	Repair or replace electric outlet. [N.J.A.C. 5:10-13.1(b)7]	N	Abated
3900822	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900826	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Bedroom-BR2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3899956	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899955	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900233	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900832	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Hallway	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900824	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Hallway	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900820	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900828	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900819	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900823	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900827	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900831	Building 1 33 MILL Street	Unit 10W, Floor 10, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900840	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR1-remove water damaged	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
			substrate before repair			
3900836	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900834	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900838	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR1-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900839	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900835	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900837	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900841	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Bedroom-BR2-remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899958	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899957	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900234	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900843	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Kitchen	Repair or replace refrigerator to maintain temperatures between 32 and 50 degrees to avoid food spoilage. [N.J.A.C. 5:10-20.1(a)5]	N	Abated
3900842	Building 1 33 MILL Street	Unit 10X, Floor 10, Building 1	Kitchen-stove/oven	Repair or replace cooking facility which is safely connected to a sufficient capacity electrical system or if gas connected to permanent fixtures and tubing to avoid the leakage of gas. *M [N.J.A.C. 5:10-20.1(a)6]	N	Abated
3900844	Building 1 33 MILL Street	Unit 10Y, Floor 10, Building 1	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N	Abated
3899960	Building 1 33 MILL Street	Unit 10Y, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899959	Building 1 33 MILL Street	Unit 10Y, Floor 10, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900235	Building 1 33 MILL Street	Unit 10Y, Floor 10, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900347	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bathroom-repair leak then repair ceiling tile	Remove from ceilings visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900341	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900343	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900345	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900344	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900346	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900342	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900340	Building 1 33 MILL Street	Unit 2A, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900352	Building 1 33 MILL Street	Unit 2C, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900371	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900370	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900369	Building 1 33 MILL Street	Unit 2E, Floor 2, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900393	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900397	Building 1 33 MILL Street	Unit 3B, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900400	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Bathroom	Repair or replace electric light fixture. [N.J.A.C. 5:10-13.1(b)7]	N	Abated
3900399	Building 1 33 MILL Street	Unit 3C, Floor 3, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3900402	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900405	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900404	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900403	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900406	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 1-repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900412	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 1-repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900408	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 1-repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900410	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Bedroom-BR 1-repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900401	Building 1 33 MILL Street	Unit 3D, Floor 3, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3900416	Building 1 33 MILL Street	Unit 3E, Floor 3, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900419	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900417	Building 1 33 MILL Street	Unit 3N, Floor 3, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900429	Building 1 33 MILL Street	Unit 3P, Floor 3, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N	Abated
3900433	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900431	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900434	Building 1 33 MILL Street	Unit 3Q, Floor 3, Building 1	Bedroom-BR 1	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900436	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900438	Building 1 33 MILL Street	Unit 3R, Floor 3, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900458	Building 1 33 MILL Street	Unit 4A, Floor 4, Building 1	Bathroom-sink/basin	Repair or replace faucet *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900463	Building 1 33 MILL Street	Unit 4B, Floor 4, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3900464	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900470	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900468	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900466	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900471	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900469	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900467	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900465	Building 1 33 MILL Street	Unit 4E, Floor 4, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900472	Building 1 33 MILL Street	Unit 4F, Floor 4, Building 1	Kitchen	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900473	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900475	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Hallway	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900477	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900479	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Hallway	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900474	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900476	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900478	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900480	Building 1 33 MILL Street	Unit 4G, Floor 4, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900484	Building 1 33 MILL Street	Unit 4J, Floor 4, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900482	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900481	Building 1 33 MILL Street	Unit 4K, Floor 4, Building 1	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900491	Building 1 33 MILL Street	Unit 4M, Floor 4, Building 1	Bathroom- shower head & faucet	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900493	Building 1 33 MILL Street	Unit 4N, Floor 4, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3900494	Building 1 33 MILL Street	Unit 4P, Floor 4, Building 1	Bathroom	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900500	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900501	Building 1 33 MILL Street	Unit 4U, Floor 4, Building 1	Kitchen- stove/oven	Repair or replace cooking facility which is safely connected to a sufficient capacity electrical system or if gas connected to permanent fixtures and tubing to avoid the leakage of gas. *M [N.J.A.C. 5:10-20.1(a)6]	N	Abated
3900510	Building 1 33 MILL Street	Unit 4W, Floor 4, Building 1	Front Door	Install chain guard on entry door(s). [N.J.A.C. 5:10-19.2(a)5]	N	Abated
3900090	Building 1 33 MILL Street	Unit 5C, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900089	Building 1 33 MILL Street	Unit 5C, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900300	Building 1 33 MILL Street	Unit 5C, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900532	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900530	Building 1 33 MILL Street	Unit 5J, Floor 5, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900534	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Front Door	Repair apartment entry door(s) so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900533	Building 1 33 MILL Street	Unit 5M, Floor 5, Building 1	Front Door	Replace apartment entry door so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900536	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Bathroom	Repair or replace wash basin. *M [N.J.A.C. 5:10-21.1(e)1]	N	Abated
3900537	Building 1 33 MILL Street	Unit 5N, Floor 5, Building 1	Stairwell/ Stairway	Occupants shall place all garbage within receptacles provided to avoid unsanitary conditions [N.J.A.C. 5:10-5.4(a)]	N	Withdrawn
3900114	Building 1 33 MILL Street	Unit 5P, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900113	Building 1 33 MILL Street	Unit 5P, Floor 5, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900312	Building 1 33 MILL Street	Unit 5P, Floor 5, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900546	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900545	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom- remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900539	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom- remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900541	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom- remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900543	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bathroom- remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900544	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bedroom- remove water damaged substrate before repair	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900540	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bedroom- remove water damaged substrate before repair	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900542	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bedroom- remove water damaged substrate before repair	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900538	Building 1 33 MILL Street	Unit 5Q, Floor 5, Building 1	Bedroom- remove water damaged substrate before repair	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900547	Building 1 33 MILL Street	Unit 5R, Floor 5, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3900548	Building 1 33 MILL Street	Unit 5S, Floor 5, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900550	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Bathroom	Repair or replace wash basin drain pipe in bathroom [N.J.A.C. 5:10-21.1(e)1]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900549	Building 1 33 MILL Street	Unit 5U, Floor 5, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900551	Building 1 33 MILL Street	Unit 5W, Floor 5, Building 1	Kitchen- repair freezer	Repair or replace refrigerator to maintain temperatures between 32 and 50 degrees to avoid food spoilage. [N.J.A.C. 5:10-20.1(a)5]	N	Abated
3900552	Building 1 33 MILL Street	Unit 5X, Floor 5, Building 1	Bathroom	Repair or replace plumbing fixture waste piping as required *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900561	Building 1 33 MILL Street	Unit 5Y, Floor 5, Building 1	Front Door	Repair apartment entry door(s) so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3899751	Building 1 33 MILL Street	Unit 6C, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899752	Building 1 33 MILL Street	Unit 6C, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900131	Building 1 33 MILL Street	Unit 6C, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900568	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900566	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900564	Building 1 33 MILL Street	Unit 6D, Floor 6, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900575	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900584	Building 1 33 MILL Street	Unit 6E, Floor 6, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899762	Building 1 33 MILL Street	Unit 6G, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899761	Building 1 33 MILL Street	Unit 6G, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900136	Building 1 33 MILL Street	Unit 6G, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900591	Building 1 33 MILL Street	Unit 6K, Floor 6, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899768	Building 1 33 MILL Street	Unit 6K, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899767	Building 1 33 MILL Street	Unit 6K, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900139	Building 1 33 MILL Street	Unit 6K, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899770	Building 1 33 MILL Street	Unit 6L, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899769	Building 1 33 MILL Street	Unit 6L, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900140	Building 1 33 MILL Street	Unit 6L, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899772	Building 1 33 MILL Street	Unit 6M, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899771	Building 1 33 MILL Street	Unit 6M, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900141	Building 1 33 MILL Street	Unit 6M, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899773	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899774	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900142	Building 1 33 MILL Street	Unit 6N, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899778	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899777	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated



Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			leaks			
3900144	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900605	Building 1 33 MILL Street	Unit 6Q, Floor 6, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3900608	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Bedroom-BR 1	Repair door frame so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Withdrawn
3900607	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Bedroom-BR 1	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Withdrawn
3899782	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899781	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900146	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900610	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entrance- entry way	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900609	Building 1 33 MILL Street	Unit 6R, Floor 6, Building 1	Entrance- entry way	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900614	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900612	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3899786	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899785	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900148	Building 1 33 MILL Street	Unit 6T, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899787	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899788	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900149	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900615	Building 1 33 MILL Street	Unit 6U, Floor 6, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3899790	Building 1 33 MILL Street	Unit 6V, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899789	Building 1 33 MILL Street	Unit 6V, Floor 6, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900150	Building 1 33 MILL Street	Unit 6V, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900618	Building 1 33 MILL Street	Unit 6V, Floor 6, Building 1	Front Door	Repair apartment entry door(s) so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3899791	Building 1 33 MILL Street	Unit 6W, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899792	Building 1 33 MILL Street	Unit 6W, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900151	Building 1 33 MILL Street	Unit 6W, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899794	Building 1 33 MILL Street	Unit 6X, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899793	Building 1 33 MILL Street	Unit 6X, Floor 6, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900152	Building 1 33 MILL Street	Unit 6X, Floor 6, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900619	Building 1 33 MILL Street	Unit 6X, Floor 6, Building 1	Front Door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900620	Building 1 33 MILL Street	Unit 6Y, Floor 6, Building 1	Front Door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899798	Building 1 33 MILL Street	Unit 7A, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899797	Building 1 33 MILL Street	Unit 7A, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900154	Building 1 33 MILL Street	Unit 7A, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899799	Building 1 33 MILL Street	Unit 7B, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899800	Building 1 33 MILL Street	Unit 7B, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900155	Building 1 33 MILL Street	Unit 7B, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899804	Building 1 33 MILL Street	Unit 7C, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899803	Building 1 33 MILL Street	Unit 7C, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900157	Building 1 33 MILL Street	Unit 7C, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900631	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900634	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900637	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900640	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900641	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900638	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900632	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900635	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900643	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N	Abated
3899810	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899809	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900160	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			plenums			
3900636	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900633	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900639	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900642	Building 1 33 MILL Street	Unit 7F, Floor 7, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900647	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900646	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900645	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900644	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899812	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899811	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900161	Building 1 33 MILL Street	Unit 7G, Floor 7, Building 1	Entire Unit-remove substances from heating/	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			cooling plenums			
3900649	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Bathroom-repair tub drain/plug	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Withdrawn
3899814	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899813	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900162	Building 1 33 MILL Street	Unit 7H, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900652	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900651	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Bathroom	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N	Abated
3899816	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899815	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900163	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900650	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Abated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900653	Building 1 33 MILL Street	Unit 7J, Floor 7, Building 1	Kitchen- stove/oven	Repair or replace cooking facility which is safely connected to a sufficient capacity electrical system or if gas connected to permanent fixtures and tubing to avoid the leakage of gas. *M [N.J.A.C. 5:10-20.1(a)6]	N	Abated
3900654	Building 1 33 MILL Street	Unit 7K, Floor 7, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N	Abated
3899818	Building 1 33 MILL Street	Unit 7K, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899817	Building 1 33 MILL Street	Unit 7K, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900164	Building 1 33 MILL Street	Unit 7K, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899820	Building 1 33 MILL Street	Unit 7L, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899819	Building 1 33 MILL Street	Unit 7L, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900165	Building 1 33 MILL Street	Unit 7L, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900655	Building 1 33 MILL Street	Unit 7M, Floor 7, Building 1	Bathroom	Repair or replace wash basin. *M [N.J.A.C. 5:10-21.1(e)1]	N	Abated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899822	Building 1 33 MILL Street	Unit 7M, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899821	Building 1 33 MILL Street	Unit 7M, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900166	Building 1 33 MILL Street	Unit 7M, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899826	Building 1 33 MILL Street	Unit 7N, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899825	Building 1 33 MILL Street	Unit 7N, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900168	Building 1 33 MILL Street	Unit 7N, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899827	Building 1 33 MILL Street	Unit 7P, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899828	Building 1 33 MILL Street	Unit 7P, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900169	Building 1 33 MILL Street	Unit 7P, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900656	Building 1 33 MILL Street	Unit 7P, Floor 7, Building 1	Kitchen- exhaust fan	Occupant shall keep cooking equipment clean, free of garbage, food particles and grease. [N.J.A.C. 5:10-5.4(f)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900658	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Bedroom-BR 2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900659	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Bedroom-BR 2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900660	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Bedroom-BR 2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900657	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Bedroom-BR 2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899830	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899829	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900170	Building 1 33 MILL Street	Unit 7Q, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899832	Building 1 33 MILL Street	Unit 7R, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899831	Building 1 33 MILL Street	Unit 7R, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900171	Building 1 33 MILL Street	Unit 7R, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899833	Building 1 33 MILL Street	Unit 7S, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899834	Building 1 33 MILL Street	Unit 7S, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900172	Building 1 33 MILL Street	Unit 7S, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899836	Building 1 33 MILL Street	Unit 7T, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899835	Building 1 33 MILL Street	Unit 7T, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900173	Building 1 33 MILL Street	Unit 7T, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900662	Building 1 33 MILL Street	Unit 7T, Floor 7, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3899838	Building 1 33 MILL Street	Unit 7U, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899837	Building 1 33 MILL Street	Unit 7U, Floor 7, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900174	Building 1 33 MILL Street	Unit 7U, Floor 7, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899840	Building 1 33 MILL Street	Unit 7V, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899839	Building 1 33 MILL Street	Unit 7V, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900175	Building 1 33 MILL Street	Unit 7V, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899842	Building 1 33 MILL Street	Unit 7W, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899841	Building 1 33 MILL Street	Unit 7W, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900176	Building 1 33 MILL Street	Unit 7W, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900663	Building 1 33 MILL Street	Unit 7W, Floor 7, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Abated
3900666	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3899843	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899844	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900177	Building 1 33 MILL Street	Unit 7X, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900669	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899848	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899847	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900179	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900670	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Hallway- closet doors	Repair door hardware so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900671	Building 1 33 MILL Street	Unit 7Y, Floor 7, Building 1	Hallway- closet doors	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900673	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Bedroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900672	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3899850	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899849	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900180	Building 1 33 MILL Street	Unit 8A, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899852	Building 1 33 MILL Street	Unit 8B, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899851	Building 1 33 MILL Street	Unit 8B, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900181	Building 1 33 MILL Street	Unit 8B, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899853	Building 1 33 MILL Street	Unit 8C, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899854	Building 1 33 MILL Street	Unit 8C, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900182	Building 1 33 MILL Street	Unit 8C, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900674	Building 1 33 MILL Street	Unit 8C, Floor 8, Building 1	Hallway-closet doors	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900676	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899855	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899856	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900183	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900675	Building 1 33 MILL Street	Unit 8D, Floor 8, Building 1	Kitchen	Repair or replace kitchen cabinets, cabinet doors or drawers to open and close properly. [N.J.A.C. 5:10-20.1(a)7]	N	Abated
3900677	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899857	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899858	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900184	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900678	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Hallway- closet door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900679	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900680	Building 1 33 MILL Street	Unit 8E, Floor 8, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899860	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899859	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900185	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900682	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Kitchen	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900681	Building 1 33 MILL Street	Unit 8F, Floor 8, Building 1	Kitchen	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900684	Building 1 33 MILL Street	Unit 8G, Floor 8, Building 1	Bathroom-repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899862	Building 1 33 MILL Street	Unit 8G, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899861	Building 1 33 MILL Street	Unit 8G, Floor 8, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900186	Building 1 33 MILL Street	Unit 8G, Floor 8, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899863	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899864	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900187	Building 1 33 MILL Street	Unit 8H, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899866	Building 1 33 MILL Street	Unit 8J, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899865	Building 1 33 MILL Street	Unit 8J, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900188	Building 1 33 MILL Street	Unit 8J, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900690	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Bathroom- repair tub drain/plug	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Withdrawn
3900688	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Bathroom- repair tub drain/plug	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Withdrawn
3900691	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Entire Unit	Eliminate Nuisance Oder which shall constitute a nuisance that is harmful or potentially harmful to the health and well-being of persons of ordinary sensitivity occupying or using the premises. [N.J.A.C. 5:10-6.2]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899870	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899869	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900190	Building 1 33 MILL Street	Unit 8K, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900693	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899872	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899871	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900191	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900692	Building 1 33 MILL Street	Unit 8L, Floor 8, Building 1	Kitchen	Repair or replace refrigerator to maintain temperatures between 32 and 50 degrees to avoid food spoilage. [N.J.A.C. 5:10-20.1(a)5]	N	Abated
3899874	Building 1 33 MILL Street	Unit 8M, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899873	Building 1 33 MILL Street	Unit 8M, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900192	Building 1 33 MILL Street	Unit 8M, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899876	Building 1 33 MILL Street	Unit 8N, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899875	Building 1 33 MILL Street	Unit 8N, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900193	Building 1 33 MILL Street	Unit 8N, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899878	Building 1 33 MILL Street	Unit 8P, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899877	Building 1 33 MILL Street	Unit 8P, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900194	Building 1 33 MILL Street	Unit 8P, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Withdrawn
3900697	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900698	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900699	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899882	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899881	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900196	Building 1 33 MILL Street	Unit 8R, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899884	Building 1 33 MILL Street	Unit 8S, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899883	Building 1 33 MILL Street	Unit 8S, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900197	Building 1 33 MILL Street	Unit 8S, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900702	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900701	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900700	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900703	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899885	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899886	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900198	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900704	Building 1 33 MILL Street	Unit 8T, Floor 8, Building 1	Kitchen- including faucets	Repair or replace kitchen sink. *M [N.J.A.C. 5:10-20.1(a)2]	N	Abated
3900707	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Bedroom- including above & beside windows	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900706	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Bedroom- including above & beside windows	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900708	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Bedroom- including above & beside windows	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900705	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Bedroom- including above & beside windows	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899888	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899887	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900199	Building 1 33 MILL Street	Unit 8U, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900713	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom- BR1	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900709	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom- BR1	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900711	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom- BR1	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900715	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom- BR1	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900712	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom- BR2	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900716	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom- BR2	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900710	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom- BR2	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900714	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Bedroom- BR2	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3899891	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899892	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
			leaks			
3900201	Building 1 33 MILL Street	Unit 8V, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899894	Building 1 33 MILL Street	Unit 8W, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899893	Building 1 33 MILL Street	Unit 8W, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900202	Building 1 33 MILL Street	Unit 8W, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899895	Building 1 33 MILL Street	Unit 8X, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899896	Building 1 33 MILL Street	Unit 8X, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900203	Building 1 33 MILL Street	Unit 8X, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899897	Building 1 33 MILL Street	Unit 8Y, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899898	Building 1 33 MILL Street	Unit 8Y, Floor 8, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900204	Building 1 33 MILL Street	Unit 8Y, Floor 8, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899900	Building 1 33 MILL Street	Unit 9A, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899899	Building 1 33 MILL Street	Unit 9A, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900205	Building 1 33 MILL Street	Unit 9A, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900717	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Bathroom	Repair or replace wash basin. *M [N.J.A.C. 5:10-21.1(e)1]	N	Abated
3900718	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899902	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899901	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900206	Building 1 33 MILL Street	Unit 9B, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900719	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated



Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3900720	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Bathroom- repair tub drain/plug	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Withdrawn
3899904	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899903	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900207	Building 1 33 MILL Street	Unit 9C, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899906	Building 1 33 MILL Street	Unit 9D, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899905	Building 1 33 MILL Street	Unit 9D, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900208	Building 1 33 MILL Street	Unit 9D, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900721	Building 1 33 MILL Street	Unit 9E, Floor 9, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899907	Building 1 33 MILL Street	Unit 9E, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899908	Building 1 33 MILL Street	Unit 9E, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900209	Building 1 33 MILL Street	Unit 9E, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899910	Building 1 33 MILL Street	Unit 9F, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899909	Building 1 33 MILL Street	Unit 9F, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900210	Building 1 33 MILL Street	Unit 9F, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900725	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Bathroom	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900724	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900723	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900722	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3899914	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899913	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900212	Building 1 33 MILL Street	Unit 9G, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899916	Building 1 33 MILL Street	Unit 9H, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899915	Building 1 33 MILL Street	Unit 9H, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900213	Building 1 33 MILL Street	Unit 9H, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900726	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899918	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899917	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900214	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900727	Building 1 33 MILL Street	Unit 9J, Floor 9, Building 1	Kitchen- secure kitchen sink faucet	Repair or replace faucet *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899920	Building 1 33 MILL Street	Unit 9K, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899919	Building 1 33 MILL Street	Unit 9K, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900215	Building 1 33 MILL Street	Unit 9K, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899922	Building 1 33 MILL Street	Unit 9L, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899921	Building 1 33 MILL Street	Unit 9L, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900216	Building 1 33 MILL Street	Unit 9L, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900729	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Bathroom	Resurface bathtub [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899924	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899923	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Entire Unit-clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900217	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Entire Unit-remove substances from heating/cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900728	Building 1 33 MILL Street	Unit 9M, Floor 9, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900733	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bathroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900730	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bathroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900736	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bathroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900731	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bedroom	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900737	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bedroom	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900734	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Bedroom	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3899926	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899925	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900218	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900732	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900738	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900735	Building 1 33 MILL Street	Unit 9N, Floor 9, Building 1	Hallway	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900739	Building 1 33 MILL Street	Unit 9P, Floor 9, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899927	Building 1 33 MILL Street	Unit 9P, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899928	Building 1 33 MILL Street	Unit 9P, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900219	Building 1 33 MILL Street	Unit 9P, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900740	Building 1 33 MILL Street	Unit 9Q, Floor 9, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899929	Building 1 33 MILL Street	Unit 9Q, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899930	Building 1 33 MILL Street	Unit 9Q, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900220	Building 1 33 MILL Street	Unit 9Q, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3899932	Building 1 33 MILL Street	Unit 9R, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899931	Building 1 33 MILL Street	Unit 9R, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900221	Building 1 33 MILL Street	Unit 9R, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900741	Building 1 33 MILL Street	Unit 9R, Floor 9, Building 1	Hallway	Repair and maintain A.C. operated fire detector system. [N.J.A.C. 5:70-3.907(8)1]	Y	Withdrawn
3900742	Building 1 33 MILL Street	Unit 9S, Floor 9, Building 1	Bathroom	Repair tub/shower tile surround and caulk [N.J.A.C. 5:10-21.1(e)]	N	Abated
3899935	Building 1 33 MILL Street	Unit 9S, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899936	Building 1 33 MILL Street	Unit 9S, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900223	Building 1 33 MILL Street	Unit 9S, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900744	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Bathroom	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N	Abated
3900743	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Bathroom- repair tub drain/plug	Repair or replace bathtub fixtures *M [N.J.A.C. 5:10-21.1(e)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3899938	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899937	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900224	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900746	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Living Room- @ sliding door	Repair door assembly so that door(s) can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900745	Building 1 33 MILL Street	Unit 9T, Floor 9, Building 1	Living Room- @ sliding door	Repair door frame so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3899940	Building 1 33 MILL Street	Unit 9U, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899939	Building 1 33 MILL Street	Unit 9U, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900225	Building 1 33 MILL Street	Unit 9U, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899942	Building 1 33 MILL Street	Unit 9V, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899941	Building 1 33 MILL Street	Unit 9V, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated



<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900226	Building 1 33 MILL Street	Unit 9V, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3899944	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899943	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3900227	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900747	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900749	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900750	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900748	Building 1 33 MILL Street	Unit 9W, Floor 9, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3899946	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3899945	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900228	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900759	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Front Door- repair lock so door can be readily opened	Repair door hardware so that door can be readily opened and closed. [N.J.A.C. 5:10-8.4]	N	Abated
3900758	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Hallway	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900752	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900756	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900754	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Hallway	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900751	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Living Room	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900753	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Living Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900757	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Living Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900755	Building 1 33 MILL Street	Unit 9X, Floor 9, Building 1	Living Room	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900766	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entire Unit	Eliminate infestation [N.J.A.C. 5:10-10.2(a)]	N	Abated

Violation ID	Bldg	Area	Location	Corrective Action	Life Safety	Status
3899947	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Maintain or repair heating system to be kept in good operating condition to provide heat supply required. [N.J.A.C. 5:10-14.3(a)]	Y	Abated
3899948	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entire Unit- clean&maintain air plenum in each unit/fix leaks	Repair or Replace heating equipment to avoid leakage*M [N.J.A.C. 5:10-14.3(b)]	N	Abated
3900229	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entire Unit- remove substances from heating/ cooling plenums	Remove from interior surfaces visible foreign matter and provide clean, sanitary and well-maintained surface. [N.J.A.C. 5:10-8.2(b)]	N	Abated
3900764	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entrance	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900762	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entrance	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900760	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Entrance	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900765	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Hallway	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900763	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Hallway	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900761	Building 1 33 MILL Street	Unit 9Y, Floor 9, Building 1	Hallway	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900901	Building 2 33 MILL Street	Building 2 - Exterior	unit 24	Repair Patio Surface. [N.J.A.C. 5:10-6.4(a)4]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900881	Building 2 33 MILL Street	Unit 10, Floor 1, Building 2	Bathroom-1st flr bath	Repair or Replace light fixture *M [N.J.A.C. 5:10-13.3(c)]	N	Abated
3900882	Building 2 33 MILL Street	Unit 10, Floor 1, Building 2	Stairwell/ Stairway	Repair or Replace light fixture *M [N.J.A.C. 5:10-13.3(c)]	N	Abated
3900888	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Bathroom	Caulk bathtub/shower [N.J.A.C. 5:10-21.1(e)]	N	Abated
3900889	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Living Room- repair leak then repair & paint	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900892	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Living Room- repair leak then repair & paint	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900891	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Living Room- repair leak then repair & paint	Repair wall to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900890	Building 2 33 MILL Street	Unit 16, Floor 1, Building 2	Living Room- repair leak then repair & paint	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900895	Building 2 33 MILL Street	Unit 24, Floor 1, Building 2	Dining Room	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900896	Building 2 33 MILL Street	Unit 24, Floor 1, Building 2	Dining Room	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900897	Building 2 33 MILL Street	Unit 24, Floor 1, Building 2	Stairwell/ Stairway	Repair or Replace light fixture *M [N.J.A.C. 5:10-13.3(c)]	N	Abated
3900963	Building 3 33 MILL Street	Building 3 - Exterior	near 30-34 & @ corner	Make leaders and drainpipes direct storm waters into draining systems and away from the foundation walls of the structure [N.J.A.C. 5:10-7.5]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900909	Building 3 33 MILL Street	Unit 30, Floor 1, Building 3	Kitchen	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900921	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-1st flr	REPAIR OR REPLACE MECHANICAL BATHROOM VENTILATION TO EXHAUST AT LEAST 50 CUBIC FEET OF AIR PER MINUTE IN ROOMS WITH 1 TOILET OR URINAL DIRECTLY TO THE OUTSIDE *M [N.J.A.C. 5:10-16.3(a)3]	N	Abated
3900919	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-1st flr	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N	Abated
3900922	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-2nd flr	REPAIR OR REPLACE MECHANICAL BATHROOM VENTILATION TO EXHAUST AT LEAST 50 CUBIC FEET OF AIR PER MINUTE IN ROOMS WITH 1 TOILET OR URINAL DIRECTLY TO THE OUTSIDE *M [N.J.A.C. 5:10-16.3(a)3]	N	Abated
3900920	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-2nd flr	Repair or Replace light fixture Kitchen/bathroom [N.J.A.C. 5:10-13.3(f)]	N	Abated
3900923	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-2nd flr	Repair ceiling to have an even and smooth surface [N.J.A.C. 5:10-8.2(a)]	N	Abated
3900924	Building 3 33 MILL Street	Unit 36, Floor 1, Building 3	Bathroom-2nd flr	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900941	Building 3 33 MILL Street	Unit 46, Floor 1, Building 3	Entire Unit	Provide admission to dwelling unit to conduct inspection. [N.J.A.C. 5:10-1.10(a)]	N	Abated
3900947	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom-2nd flr	PAINT CEILING WITH AN APPROPRIATE PROTECTIVE COATING. [N.J.A.C. 5:10-8.2(c)]	N	Abated

<b>Violation ID</b>	<b>Bldg</b>	<b>Area</b>	<b>Location</b>	<b>Corrective Action</b>	<b>Life Safety</b>	<b>Status</b>
3900944	Building 3 33 MILL Street	Unit 48, Floor 1, Building 3	Bathroom-2nd flr	PAINT WALLS WITH AN APPROPRIATE PROTECTIVE COATING [N.J.A.C. 5:10-8.2(c)]	N	Abated
3900956	Building 3 33 MILL Street	Unit 52, Floor 1, Building 3	Bathroom	Repair faucet bathtub/shower *M [N.J.A.C. 5:10-21.1(e)]	N	Abated

**IMPORTANT NOTICE TO OWNERS**  
**(PLEASE READ CAREFULLY)**

IF YOUR BUILDING WAS BUILT BEFORE 1978 AND IT IS NOT CERTIFIED AS BEING LEAD FREE, ALL WORK PERFORMED TO ABATE PAINTING VIOLATIONS OR VIOLATIONS THAT DISTURB PAINTED SURFACES SHALL BE CARRIED OUT USING LEAD SAFE WORK PRACTICES BY INDIVIDUALS TRAINED IN ACCORDANCE WITH N.J.A.C.5:10-6.6(g). UPON RE-INSPECTION, THE PROPERTY OWNER MUST HAVE AVAILABLE FOR THE INSPECTORS REVIEW, ANY TRAINING RECORDS TO SUPPORT COMPLIANCE WITH N.J.A.C. 5:10-6.6(g), AS WELL AS ANY REQUIRED WIPE SAMPLES SHOWING THE WORK AREA TO BE LEAD HAZARD FREE. IF THERE IS DOCUMENTATION INDICATING THAT THE SURFACES CITED DO NOT CONTAIN LEAD BASED PAINT, THEN ALL WORK MUST COMPLY WITH N.J.A.C. 5:10-8.2.

**PERMIT INFORMATION (CORRECTIVE ACTION WITH THE FOLLOWING FOOTNOTE)**

'P' - A CONSTRUCTION PERMIT IS REQUIRED FROM THE CONSTRUCTION OFFICIAL. COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE CONSTRUCTION OFFICIAL'S APPROVALS OF WORK COMPLETED MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE BUREAU OF HOUSING INSPECTION HAS COMPLETED IT'S RE-INSPECTION. 'M' - A CONSTRUCTION PERMIT MAY OR MAY NOT BE REQUIRED CONTINGENT UPON THE EXTENT OF THE REQUIRED WORK TO ABATE THE CITED VIOLATION(S). COPIES OF THE ISSUED CONSTRUCTION PERMITS AND THE CONSTRUCTION OFFICIAL'S APPROVAL OF WORK MUST BE PROMINENTLY DISPLAYED IN THE IMMEDIATE VICINITY OF THE WORK PERFORMED UNTIL THE BUREAU OF HOUSING INSPECTION HAS COMPLETED ITS RE-INSPECTION.

**VIOLATIONS - RE-INSPECTIONS**

A re-inspection will take place some time after the "Re-inspection Date" which is noted on the enclosed penalty, but no earlier than 30 days from which this inspection report was delivered or served. If you have any questions, contact the Bureau at (609) 633-6225 or (609) 633-6210.

When a re-inspection is conducted, certain VALUES will be entered in the status column of the inspection report. "Unabated" = violation not corrected; "UNDETERMINED"= no admission to the area; "ADMINISTRATIVE" = violation not corrected; "UNDER APPEAL" = active hearing request; "UNDER EXTENSION" = granted extension of time to abate.

**INSPECTION FEE PAYMENT**

The Order to Pay Inspection Fee received with this report must be returned with the fee (SPECIFIED ON INVOICE) within 30 days of the day it was delivered or served. Payments may be made online at the Division of Codes and Standards website ([www.nj.gov/dca/divisions/codes](http://www.nj.gov/dca/divisions/codes)) under the DCA RIMS Online Services link. You may also mail your payment with the invoice stub to State of New Jersey, DCA BHI - DORES, PO Box 662, Trenton, NJ 08646-0662. If payment is not received within 30 days, a penalty will be assessed in the amount of \$50.00 or 50% of the inspection fee, whichever is greater up to \$500.00 maximum.

The Certificate of Inspection cannot be issued until all violations have been corrected, all fees and penalties have been paid, and the Certificate of Registration has been issued to the current owner. If you have any questions, contact the Bureau at (609) 633-6225 or (609) 633-6210.

### **HEARING REQUEST**

You have the right to contest these orders at an administrative hearing. The timeframe with which to contest the existence of said violations has expired but you may contest the compliance status of any violation for which a violation penalty has been issued and enclosed with this inspection report.

Requests may be submitted online at the Division of Codes and Standards website ([www.nj.gov/dca/divisions/codes/](http://www.nj.gov/dca/divisions/codes/)) under the DCA RIMS Online Services link. Click "Submit an Appeal Request". Requests **MUST BE MADE WITHIN 15 DAYS AFTER THESE ORDERS WERE DELIVERED AND SERVED.**

Requests not submitted online **MUST BE MADE IN WRITING AND MUST BE POSTMARKED WITHIN 15 DAYS AFTER THESE ORDERS WERE DELIVERED AND SERVED.** Requests must set forth in detail all issues, **FACTUAL, LEGAL or PROCEDURAL**, intended to be raised at the hearing as any issue not so raised shall be deemed waived. Please be sure to include, with your request, the property address, registration number, and the date by which all violations must be corrected and mail to **HEARING COORDINATOR, BUREAU OF HOUSING INSPECTION, PO BOX 810, TRENTON, NJ 08625-0810**

A corporation must be represented only by: (1) a licensed attorney; or (2) a person who submits a written statement bearing the corporate seal which specifies that, by means of corporate resolution, he/she has been authorized as corporate agent in this matter.

You will be notified of the time and place of the hearing which shall be held pursuant to Section 18 of the Hotel and Multiple Dwelling Law and the Administrative Procedures Act. If you have any questions, contact the Bureau of Housing Inspection Hearing Coordinator at (609) 633-6216.

### **EXTENSION REQUEST**

You may request an extension of time to correct any violation(s). By requesting an extension with respect to a violation, one expressly waives the right to a hearing as to that violation and concedes that the Inspection Report and Orders are correct and free from procedural or substantive defects as to that violation. While the extension request is being considered, the re-inspection date on the enclosed penalty, by which all violations must be corrected, does not change and remains the same for any violation for which an extension was denied.

Extension requests **MUST BE SUBMITTED TWO (2) WEEKS PRIOR TO THE RE-INSPECTION DATE ON THE ENCLOSED PENALTY.**

Requests may be submitted online at the Division of Codes and Standards website ([www.nj.gov/dca/divisions/codes/](http://www.nj.gov/dca/divisions/codes/)) under the DCA RIMS Online Services link. Click "Request an Extension" under the Bureau of Housing Inspection.

Requests ***not*** submitted online must be made in writing and must state in detail: (1) the violations corrected to date; (2)



the reason why each uncorrected violation cannot be corrected prior to the re-inspection date on the enclosed penalty; and (3) the date by which all violations will be corrected. Please be sure to include the property address, registration number and the date by which all violations must be corrected in your request for an extension and mail to: BUREAU OF HOUSING INSPECTION (EXTENSIONS), PO BOX 810, TRENTON, NJ 08625-0810.

### **REGULATIONS AND CODES**

Corrective Actions prefixed by "5:10-" on this Inspection Report and Orders of the Commissioner refer to violations cited pursuant to the Regulations for Maintenance of Hotels and Multiple Dwellings N.J.A.C. 5:10-1 et seq. These regulations along with the New Jersey Multiple Dwelling Law N.J.S.A 55:13A-1 et. seq. are available online at the Department of Community Affairs, Division of Codes and Standards, Bureau of Housing Inspection website at: <http://www.nj.gov/dca/divisions/codes/offices/housinginspection.html>.

Corrective Actions prefixed by "5:70-" refer to violations cited under the New Jersey Uniform Fire Code N.J.A.C. 5:70-1 et. seq., which is available online at the Department of Community Affairs, Division of Fire Safety's website at: <http://www.nj.gov/dca/divisions/dfs/codes>.